Oil Field Environmental Incident Summary

Responsible Party: Schlumberger Well Service

Well Operator: WHITING OIL AND GAS CORPORATION

Well Name: OBRIGEWITCH 11-29PHU

Field Name: BELL Well File #: 31158

Date Incident:1/13/2016Time Incident:13:00Facility ID Number:County:STARKTwp:140Rng:99Sec:29Qtr:

Location Description:

Submitted By: Allison Christensen Received By:

Contact Person: Jeff Rogers

13959 50th St NW Williston, ND 58801

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:0.3 MileDistance Nearest Water Well:0.3 Mile

Type of Incident: Equipment Failure

Release Contained in Dike: Yes - On Constructed Well Site Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine 35 Barrels 30 Barrels 30 barrels

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: 6/27/2016 Clean Up Concluded: 2/13/2016

Risk Evaluation:To be determined

Areal Extent:

40'x40'

Potential Environmental Impacts:

To be determined

Action Taken or Planned:

A Vac truck was able to recover 30 bbls of fluid and return back to frac tanks. The remaining impacted facility soil will be excavated and tested to ensure all impacted soil is removed after the frac job is complete.

Wastes Disposal Location: to an approved disposal

Agencies Involved:

Updates

Date: 1/14/2016 Status: Reviewed - Assigned to Other Agency Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release remained on location according to the report. NDIC retains oversight.